





THE

ONTARIO WATER RESOURCES

COMMISSION

WATER POLLUTION SURVEY

OF THE

VILLAGE OF PORT PERRY

COUNTY OF ONTARIO

1964



THE

ONTARIO WATER RESOURCES OCT 28 1965

Report

on

WATER POLLUTION SURVEY

of the

VILLAGE OF PORT PERRY

in the

COUNTY OF ONTARIO

Division of Sanitary Engineering July 6, 1964



Report on

WATER POLLUTION SURVEY

of the

VILLAGE OF PORT PERRY

INDEX	Page Number
Introduction	1
Interviews with Officials	1
Village of Port Perry	1
Lake Scugog at Port Perry	1
Water Uses	2
Water Supply	2
Surface Water Drainage	3
Sanitary Waste Disposal	3
Industry	3
Private Outfalls	4
Sampling Procedure	4
Interpretation and Significance of Laboratory Results	5
Sample Results	6
Summary	7
Recommendation	8
APPENDICES	

Laboratory Results

Map of the Village of Port Perry

no rangel

TATES POLICITON SURVEY

of the

THE PART OF PARTY

WATER POLLUTION SURVEY

of the

VILLAGE OF PORT PERRY

INTRODUCTION

A water pollution survey of the Village of Port Perry was performed on July 6, 1964. Surveys of this type are made by the Division of Sanitary Engineering, Ontario Water Resources Commission, in order to locate active and potential sources of surface water pollution. Recommendations are made concerning the abatement of conditions which adversely affect water quality.

Similar surveys were made previously at Port Perry by

Commission staff in 1958 and in 1962. Therefore, this recent survey

was performed to review conditions revealed previously, and to

ascertain if progressive action is being taken where necessary.

INTERVIEWS WITH OFFICIALS

A discussion was held on July 6, 1964, with Mr. J. F. Raines, Clerk-Treasurer. An unsuccessful attempt was made on July 6 to contact Dr. G. M. Rennie, Medical Officer of Health.

VILLAGE OF PORT PERRY

Port Perry is situated on the west shoreline of Lake Scugog near its southern extremity. According to the 1964 Municipal Directory, the population of the village is 2,353. The area of the municipality is approximately 700 acres.

LAKE SCUGOG AT PORT PERRY

Lake Scugog tends to have a marshy shoreline. Fed by these marshy areas and numerous small tributaries, the lake waters flow in a northerly direction into the Scugog River which eventually empties into Sturgeon Lake after flowing through the Town of Lindsay.

LUASAS MULTUTION NELVE

0.000 711

VALUE TARRE OF TRAILITY

HOLTOUGON'ILL

A vector of the policy of the vector of the village of the by the performs of the part of the type of the by the straight of the state of the by the state of the

Stellar survey were tide previously at Post Durry by
Commission scale to 1958 and in 1962. Therefore, and a servey
are performed to rowfee conditions revenied previously, and to
accorded if processains and/or is being toles where percently.

Addender of the company of the state of the

Perc Percy to attracted on the west shoreline of Take Songon more its sensions succeeding, percentage to the 1964 Mentelph Biractory, the population of the quillings in 5,353. The same of the sensingsling to exproplements 700 screen.

DESCRIPTION TA NAMED COLL

these matrice about the same and amount of the lake county of the lake county that a county of the same and t

WATER USES

Municipal

Port Perry obtains its municipal water supply from ground water sources and therefore does not rely on Lake Scugog for this requirement. The lake receives untreated or inadequately treated waste flows from Port Perry and might be the receiving water for the effluent from any future sewage works there.

Industrial

Industrial water requirements at Port Perry are fulfilled by the municipal water supply in most instances.

Recreational

Extensive use is made of Lake Scugog at Port Perry for boating.

WATER SUPPLY

The water supply for the village is obtained from two drilled wells which are located south of Port Perry in the Township of Reach. Well No. 1 was developed by the village in 1948. Well No. 2 was established during 1957 with assistance from this Commission.

Problems have been encountered concerning the presence of iron and hydrogen sulphide in both water supplies, with iron bacteria in the entire water works, and sulphate reducing bacteria in the distribution system. Members of the OWRC staff have investigated these problems during the past year and have recommended measures to alleviate the objectionable conditions. Chlorination practices were initiated at Well No. 2 during 1963 for the control of iron bacteria. Chlorination facilities are not provided at Well No. 1.

Water storage is provided by a steel standpipe having a

Digitized by the Internet Archive in 2024 with funding from University of Toronto

capacity of 300,000 gallons and which was erected during 1961 on the east side of Silver Street near Queen Street.

SURFACE WATER DRAINAGE

Municipal storm sewer systems and ditches conduct run-off flows either directly to Lake Scugog or to small watercourses which empty into the lake. The principal creek is designated on the appended map as Watercourse "A", and has its source beyond the southern limit of the village. Watercourses "B" and "C" have their sources within the municipality and drain low-lying areas to Lake Scugog. Surface run-off was minimal during this survey due to dry weather conditions.

SANITARY WASTE DISPOSAL

Private sewage disposal facilities are employed in Port
Perry due to the absence of municipal sewage works. Problems have
been encountered with respect to malfunctioning systems due, in
part, to limited land areas available for the installation of
adequate tile bed systems. Reportedly, there are instances where
septic tank effluent is discharged to storm sewers or surface water
drainage systems.

The local municipal officials have engaged the services of a firm of consulting enigneers for the preparation of a preliminary engineering report on sewage works for the village.

INDUSTRY

The principal industrial firms located in Port Perry are listed as follows:

Name of Firm

H. W. Gossard Limited Ideal Dairy Products Limited

J. J. Gibson and Son Limited

Product

Undergarments
Minor production of
dairy products
Processing of poultry



Name of Firm

Lake Scugog Lumber Company Limited
Port Perry Beverages Limited
Port Perry Packers Limited

Product

Building products Carbonated drinks Processing of poultry

With respect to premises where industrial waste flows are produced, the following comments are provided:

According to information received previously, any industrial waste produced at the Ideal Dairy Products Limited plant is discharged to the municipal storm sewer on Mary Street.

A sub-surface sewage disposal system receives industrial waste flows at the J. J. Gibson and Son Limited poultry processing plant.

Wash water containing some caustic material is discharged from the Port Perry Beverages Limited plant to the marsh nearby. There was no opportunity for sampling the waste during this survey.

The liquid industrial waste produced at the Port Perry Packers Limited premises is discharged to a septic tank and thence to a waste stabilization pond. Reportedly, the waste does not overflow from this treatment facility.

PRIVATE OUTFALLS

Although private waste outfalls might exist to some extent in Port Perry, such outfalls were not revealed during this survey. .

SAMPLING PROCEDURE

Samples were collected from municipal storm sewers and ditches where flows were evident during this survey. Samples were obtained also from the three watercourses which empty into Lake Scugog within the village. Appended to this report is a map showing the locations of the sampling points. The pertinent laboratory results are appended to this report in Tables I to IV, inclusive.



The atmospheric temperature prevailing during the period of sampling on July 6 was approximately 80 degrees Fahrenheit.

INTERPRETATION AND SIGNIFICANCE OF LABORATORY RESULTS

The analyses employed to determine the quality of samples were: biochemical oxygen demand (BOD), solids, and the enumeration of coliform organisms.

The BOD of sewage, industrial wastes, or polluted waters, is the oxygen required during stabilization of the decomposible organic or chemical material by aerobic biochemical action. A fiveday BOD determination with incubation at 20 degrees Centigrade is reported. A high BOD is indicative of organic or chemical pollution. The BOD of a watercourse should not exceed four parts per million (ppm).

The analyses for solids include tests for total, suspended, and dissolved solids. The results are reported in ppm. The first test measures both the solids in solution and in suspension. The test for suspended solids indicates the measure of undissolved solids of organic or inorganic nature in suspension. Land erosion, sewage, and industrial wastes, are significant sources of suspended solids. The dissolved solids are a measure of those solids in solution.

The coliform count is employed to obtain an enumeration of coliform organisms. The presence of coliforms indicates pollution by human or animal excrement, or by some non-faecal forms. The number of coliforms is reported per 100 millilitres (ml) of the sample. The membrane filter technique was used in the examination of these samples. It is the opinion of this Commission that the presence of coliforms in a watercourse should not exceed 2,400 organisms per 100 ml of water.



SAMPLE RESULTS

The laboratory results of analyses and examinations performed on the samples collected are tabulated in appendices to this report as follows:

Tabel I - Outfalls from Port Perry to Lake Scugog Table II - Samples pertinent to Watercourse "A" Table III - Samples pertinent to Watercourse "B" Tabel IV - Samples pertinent to Watercourse "C"

Outfalls from Port Perry to Lake Scugog

Of the municipal storm sewers and ditches which terminate on the lakeshore in Port Perry, flow was evident only at the storm sewer outfall which is located at the foot of Mary Street. The pertinent laboratory results confirm the presence of sewage flows in the samples obtained at this outfall (sampling point number TS.179.58W).

Samples Pertinent to Watercourse "A"

The laboratory results reveal that this watercourse receives untreated or inadequately treated sewage flows within the village.

A high coliform content was revealed in the flows discharging to the west bank of Watercourse "A" on the north side of Elgin Street (sampling point number TSA.179.81D West).

It is obvious that waste gains access through undisclosed outfalls to this creek in the central part of the village.

Samples Pertinent to Watercourse "B"

The presence of sewage was indicated in this watercourse at Perry Street (sampling point number TSB.179.53). Samples were not collected from this creek at the road near the lakeshore because, at this point, the creek water was approaching lake level and might be diluted by lake water.



Samples Pertinent to Watercourse "C"

A high coliform content was revealed in the sample obtained from this watercourse at sampling point TSC.179.31 which is located upstream from the marshy lakeshore.

SUMMARY

A water pollution survey of the Village of Port Perry was performed by Commission staff on July 6, 1964, to review conditions which had been investigated previously in 1958 and in 1962.

Sewage flows are discharged either to municipal storm sewers extending to Lake Scugog, or to small watercourses emptying into the lake. Apparently, the discharging of untreated or inadequately treated sewage to surface waters in Port Perry results, in many instances, from the lack of adequate space for private sewage disposal systems. It is obvious that municipal sanitary sewers are required in at least the more problematic sections of the village. The need for sewage works is apparent in order to minimize any adverse effects on the quality of the receiving water. The discharging of sewage to surface water provides nutrification thereof which can exert undesirable effects on aquatic life. In addition, sewage can impair the quality of water for normal requirements.

The local municipal officials have engaged a firm of consulting engineers to prepare a preliminary report on sewage works for the village.



RECOMMENDATION

The municipal officials at Port Perry are urged to initiate a sewage works project for the village in order to abate the local sewage disposal problems.

All of which is respectfully submitted,

District Engineer:

Approved by:

K. H. Sharpe, Director



TABLE 1

OUTFALLS FROM PORT PERRY TO LAKE SCUGOG

PPM UNLESS OTHERWISE INDICATED

ALL SAMPLES EXCEPT PH REPORTED IN

SAMPLE POINT NO.		5-DAY	SOLIDS	BACTER IOLOGICAL EXAMINATION
	מסטערפ		TOTAL SUSP. DISS.	COLIFORMS/100 ML M.F.
	DRAINAGE COURSE TERMINATING ON SHORE OF LAKE SCUGOG NORTH OF SCUGOG STREET.		NO FLOW	
	DRAINAGE COURSE TERMINATING ON SHORE OF LAKE SCUGOG NORTH OF SAMPLING POINT TS.179.77D		NO FLOW	
	MUNICIPAL STORM SEWER ON SOUTH SIDE OF CASIMIR STREET - DISCHARGING TOWARD THE LAKESHORE		NO FLOW	
	MUNICIPAL STORM SEWER OUTLET ON LAKESHORE AT FOOT OF MARY STREET (PARTLY SUBMERGED - VICINITY SAMPLE)	72.0	610 88 522	000,001
	MUNICIPAL STORM SEWER OUTLET ON LAKESHORE AT FOOT OF QUEEN STREET		NO FLOW	



TABLE 11

SAMPLES PERTINENT TO WATERCOURSE "A"

PH REPORTED IN

ALL SAMPLES EXCEPT PH REPORTED IN PPM UNLESS OTHERWISE INDICATED

						RACTEDIOLOGICAL
SAMPLE		5-DAY		SOLIDS		EXAMINATION
- NO NO	SOURCE	BOD	TOTAL	SUSP.	DISS.	COLIFORMS/100 ML M.F.
TSA.179.42	WATERCOURSE "A" AT ROAD UPSTREAM FROM MOUTH	3.0	328	14	344	48,000
TSA.179.53	WATERCOURSE "A" AT NORTH STREET	9.2	210	15	495	178,000
TSA.179.77	WATERCOURSE "A" AT LILLA STREET	ł	8	8	1	44,000
TSA.179.81(E)D	DITCH TO WATERCOURSE "A" AT ELGIN STREET - EAST BANK, NORTH SIDE OF STREET		0 2	FLOW		
TSA.179.86(E)D	DITCH TO WATERCOURSE "A" AT ELGIN STREET - EAST BANK, SOUTH SIDE OF STREET		0	F 0 W		
TSA.179.81(W)D	DITCH TO WATERCOURSE "A" AT ELGIN STREET - WEST BANK, NORTH SIDE OF STREET	# #	1	;	\$ 8	150,000
TSA.179.86(W)D	DITCH TO WATERCOURSE "A" AT ELGIN STREET - WEST BANK, SOUTH SIDE OF STREET		0 N	FLOW		
TSA.179.89(N)D	DITCH TO WATERCOURSE "A" AT CRANDLE STREET - NORTH BANK, EAST SIDE OF STREET		0	FLOW		
TSA.179.86(W)D	DITCH TO WATERCOURSE "A" AT CRANDLE STREET - SOUTH BANK, EAST SIDE OF STREET		0	FLOW		
TSA.179.91	WATERCOURSE "A" AT CRANDLE STREET	1 0	8 18	:	;	44,000
TSA.180.05	WATERCOURSE "A" AT SCUGOG STREET	9*0	862	4	828	15,000



ALL SAMPLES EXCEPT PH REPORTED IN PPM UNLESS OTHERWISE INDICATED

SAMPLES PERTINENT TO WATERCOURSE "B"

BACTER I O L O G I CAL EXAM I NATION	COLIFORMS/100 ML M.F.	79,000		
	DISS.	256	SAMPLING	
SOLIDS	SUSP.	ω	INSUFFICIENT FLOW FOR SAMPLING	FLOW
	TOTAL	572	SUFFICIEN	NO FLOW
5-DAY	ВОД	0.11	Gran wood	
	SOURCE	WATERCOURSE "B" AT PERRY STREET	MUNICIPAL STORM SEWER OUTFALL ON WEST BANK OF WATERCOURSE "B" - NORTH SIDE OF PAXTON STREET.	WATERCOURSE "B" SOUTH OF PAXTON STREET
SAMPLE	POINT NO.	TSB.179.53	TSB.179.54W	TSB.179.56



ALL SAMPLES EXCEPT PH REPORTED IN PPM UNLESS OTHERWISE INDICATED

SAMPLES PERTINENT TO WATERCOURSE "C"

BACTERIOLOGICAL	EXAMINATION	COLIFORMS/100 ML M.F.	63,000
		DISS.	658
	SOL IDS	SUSP.	34
		TOTAL	692
	5-DAY	800	3,3
		SOURCE	WATERCOURSE "C" AT ROAD UPSTREAM FROM MOUTH
	SAMPLE	POINT NO.	TSC.179.31

THE PARTY OF THE P

and leavest traderial locations of

Mary In State of State of



